Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 WING HAL090024 12/09/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 918 FITZGERALD STREET BROOKDALE MONROE SQUARE 1 MONROE, NC 28112 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE FACH DEPICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DATE DEFICIENCY) (C 000) Initial Comments {C 000} This report is of a Followup Survey done by Bob Getchell and Ed Miller on December 9, 2015. The followup survey revealed that all deficiencies have not been corrected, therefore a new plan of correction is required. (C 166): Housekeeping-Maintained Free of Hazards (C 166) SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND **FURNISHINGS** (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards: (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: Based on Observation, the facility falled to provide an environment in accordance with this Rule, by not maintaining the HVAC/ventilation, grilles and their associated dampers free of hazards. Spa Shower room nationion dampers cleaned from Followup Findings on December 9, 2015: a) The Spa Shower Room return HVAC and ventilation grilles and their radiation dampers have an excessive accumulation of dust/lint, and, a radiation damper is activated. radiation damper. Pictures emaked on December 15th QD willer, Departm Health and Homan Services of worden as.

ivision of Health Service Regulation

ABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

ration(T sw

ساسان

9600

J3UJT22